

## Oxi Solid Block Bath Test Methods and Accessories

Items required for each test		ASTM D525, D873, IP 40, IP 138	ASTM D5304
15600-0	Seta Pressure Gauge		<b>A</b>
15802-2	Oxidation Vessel	•	
15803-0	Vessel Bench Clamp and Holder	•	•
15805-0	Spanner	•	•
15810-0	Liner with Cover (pack of 3)	•	•
22750-3	Digital Stopwatch		
99100-2	Analytical Balance	•	•
99200-2	Laboratory Drying Oven	•	•
ASTMS22C	Low Haz Thermometer with Certificate of Conformity	•	
ASTMST61C	Low Haz Thermometer with Works Certificate		•

Items marked ▲ are options for pressure monitoring